

Southeastern Aircraft Sales & Service
Phone: 772/461-8924 Fax: 772/461-9050

TURBINE AIRCRAFT INFORMATION

AIRCRAFT INFORMATION

Date: 01/29/21

| | | | |
|--------|--------------------|------------|------------------|
| YEAR | <u>2007</u> | MODEL | <u>AT-802A</u> |
| MAKE | <u>Air Tractor</u> | SERIAL NO. | <u>802A-0259</u> |
| REG. # | <u>N4265D</u> | | |

| | |
|------------------------|---|
| TAC READING | <u>5917.2 hrs.</u> |
| TOTAL TIME | <u>5917.2 hrs.</u> |
| ANNUAL INSPECTION DATE | <u>New at sale</u> |
| DAMAGE HISTORY | <u>Repair L & R wing tip and rudder due to storm damage</u> |

ENGINE

PROP

| | |
|----------------|----------------------------|
| MAKE | <u>PRATT & WHITNEY</u> |
| MODEL | <u>PT6A-67AG</u> |
| SN | <u>PCE-RD0162</u> |
| TIME T.T. | <u>5917.2 hrs</u> |
| TIME LIGHT O/H | <u>3320.6 hrs</u> |
| TIME H.S.I. | <u>0 hrs.</u> |
| GEAR BOX | <u>3320.6 hrs.</u> |
| SOURCE | <u>Log books</u> |

| | |
|----------------|------------------------------|
| MAKE | <u>HARTZELL</u> |
| MODEL | <u>HC-B5MA-3D</u> |
| SN | <u>HBA-2006</u> |
| TIME T.T. | <u>2395.6 hrs.</u> since new |
| Reseal/Inspect | <u>930.4 hrs.</u> |

AIRCRAFT DESCRIPTION

T.T. on landing gear 930.4 hrs. / Spar caps due 8000 hrs.
Satloc Bantam, radio pkg., smoker, electric fan brake, CP nozzles, S/S center boom, Fast Start, factory heat & air, dual A/C condensers, s/s camlocs, recent refurb., new engine mount, new paint, new glass, fresh annual and more.

\$595,000.00